Division of Health Service Regulation

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING: 01 B. WING HAL100002 03/27/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE WEST BURNSVILLE CHURCH ROAD **MOUNTAIN MANOR ASSISTED LIVING BURNSVILLE, NC 28714** SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX **PREFIX** DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) C 000 Initial Comments C 000 Report of Biennial Construction Survey by Dennis Harrell on 3-27-2015. Records indicate that this facility was first licensed on 11-1-1974, for 29 beds. Based on this information, we are requiring the facility to meet the 1967 NC Building Code, the 1971 Minimum and Desired Standards and Regulations for Homes for the Aged and Infirm, and the applicable portions of the current rules for Adult Care Homes of Seven or More Beds. C 111 Must Have Current San. & Fire Safety Reports C 111 SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION( f) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: Based on a review of documents, the required annual fire alarm system inspection report could not be located. Fire alarm systems that are not inspected and approved as required could result in the fire alarm system not operating properly in the event of an actual fire. C 185 Fire Safety-Rehearsals on Each Shift C 185 SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0309 PLAN FOR **EVACUATION** (b) There shall be rehearsals of the fire plan quarterly on each shift in accordance with the requirement of the local Fire Prevention Code

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION  A. BUILDING: 01			(X3) DATE SURVEY COMPLETED						
HAL100002			B. WING			03/27/2015						
NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE												
MOUNTAIN MANOR ASSISTED LIVING  WEST BURNSVILLE CHURCH ROAD  BURNSVILLE, NC 28714												
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES 'MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORR (EACH CORRECTIVE ACTION S CROSS-REFERENCED TO THE AF DEFICIENCY)	(X5) COMPLETE DATE							
C 185	Enforcement Official (c) Records of rehe and copies furnishes social services anninclude the date and shift, staff members description of what (f) This Rule shall a facilities.  This Rule is not me Based on a review fire plan rehearsals	al. earsals shall be maintained ed to the county department of ually. The records shall d time of the rehearsals, the s present, and a short the rehearsal involved. apply to new and existing	C 185									
C 189	SECTION .0300 - F 10A NCAC 13F .03 REQUIREMENTS (a) The building an mechanical, and plu care home shall be operating condition (k) This Rule shall facilities with the ex	11 OTHER  d all fire safety, electrical, umbing equipment in an adult maintained in a safe and	C 189									
	fire rated walls and, in several locations are not sealed with one-hour fire rated possibility that a fire quickly spread to of Findings include:	et as evidenced by: vation the required one-hour for ceilings were compromised. Holes and penetrations that materials approved for use in construction present the e that begins in one space can ther areas of the facility.  Toam was used to seal many										

Division of Health Service Regulation

STATE FORM 8EQ021 If continuation sheet 2 of 3

Division of Health Service Regulation

NAME OF PROVIDER OR SUPPLIER  STREET ADDRESS, CITY, STATE, ZIP CODE  WEST BURNSVILLE CHURCH ROAD  BURNSVILLE, NC 28714  PRIETRY  GRANDBERGENOW MUST BE PRECEDED BY PILL  REGULATORY OR LSC IDENTIFYING INFORMATION)  C 189  C 189	STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>		(X3) DATE SURVEY COMPLETED							
MOUNTAIN MANOR ASSISTED LIVING  WEST BURNSVILLE CHURCH ROAD BURNSVILLE, NC 28714  (x4) ID PREFIX TAG  SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG  CONFIDENT (EACH OF CICIENCY MUST BE PRECEDED BY FULL TAG  CONFIDENT TAG  COntinued From page 2  holes throughout the facility. Fire foam is not approved for use in Institutional Occupancies. Locations include; i. Main office, ii. Utility closet on Short Hall, iii. Utility closet on Long Hall. b. Ceiling damaged by a water pipe in utility closet on Long Hall.  2. Based on observation, one attic draft stop door was found to be open. When draft stop doors are left open, the draft stop cannot perform its function of limiting airflow in the event of a fire in the attic.  3. Based on observation, the cast iron lavatory has become loosely mounted to the wall in the Women's bathroom on the Long Hall. The lavatory could be dangerous to residents should it	HAL100002		HAL100002	B. WING		03/27/2015							
C 189   Continued From page 2   holes throughout the facility. Fire foam is not approved for use in Institutional Occupancies. Locations include; i. Main office, ii. Utility closet on Long Hall. b. Ceiling damaged by a water pipe in utility closet on Long Hall. 2. Based on observation, one attic draft stop door was found to be open. When draft stop doors are left open, the draft stop cannot perform its function of limiting airflow in the event of a fire in the attic.    SUMMARY STATEMENT OF DEFICIENCISS   ID   PROVIDER'S PLAN OF CORRECTION SHOULD BE (EACH CORRECTIVE ACTION SHOULD BE (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DATE	· · · · · · · · · · · · · · · · · · ·												
C 189   Continued From page 2   C 189   Continued From page 2   holes throughout the facility. Fire foam is not approved for use in Institutional Occupancies. Locations include; i. Main office, ii. Utility closet on Long Hall. b. Ceiling damaged by a water pipe in utility closet on Long Hall. b. Ceiling damaged by a water pipe in utility closet on Long Hall.  2. Based on observation, one attic draft stop door was found to be open. When draft stop doors are left open, the draft stop cannot perform its function of limiting airflow in the event of a fire in the attic.  3. Based on observation, the cast iron lavatory has become loosely mounted to the wall in the Women's bathroom on the Long Hall. The lavatory could be dangerous to residents should it	MOLINTAIN MANOR ASSISTED LIVING												
holes throughout the facility. Fire foam is not approved for use in Institutional Occupancies. Locations include; i. Main office, ii. Utility closet on Short Hall, iii. Utility closet on Long Hall. b. Ceiling damaged by a water pipe in utility closet on Long Hall.  2. Based on observation, one attic draft stop door was found to be open. When draft stop doors are left open, the draft stop cannot perform its function of limiting airflow in the event of a fire in the attic.  3. Based on observation, the cast iron lavatory has become loosely mounted to the wall in the Women's bathroom on the Long Hall. The lavatory could be dangerous to residents should it	PREFIX	(EACH DEFICIENCY	MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO	LD BE	COMPLETE						
approved for use in Institutional Occupancies. Locations include; i. Main office, ii. Utility closet on Short Hall, iii. Utility closet on Long Hall. b. Ceiling damaged by a water pipe in utility closet on Long Hall.  2. Based on observation, one attic draft stop door was found to be open. When draft stop doors are left open, the draft stop cannot perform its function of limiting airflow in the event of a fire in the attic.  3. Based on observation, the cast iron lavatory has become loosely mounted to the wall in the Women's bathroom on the Long Hall. The lavatory could be dangerous to residents should it	C 189	Continued From pa	ge 2	C 189									
	C 189	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)  Continued From page 2  holes throughout the facility. Fire foam is not approved for use in Institutional Occupancies. Locations include; i. Main office, ii. Utility closet on Short Hall, iii. Utility closet on Long Hall. b. Ceiling damaged by a water pipe in utility closet on Long Hall.  2. Based on observation, one attic draft stop door was found to be open. When draft stop doors are left open, the draft stop cannot perform its function of limiting airflow in the event of a fire in the attic.  3. Based on observation, the cast iron lavatory has become loosely mounted to the wall in the Women's bathroom on the Long Hall. The lavatory could be dangerous to residents should it		C 189									

Division of Health Service Regulation STATE FORM